

# WELDING HELMET

## SAVAGE A41 Air

The Savage A41 Air incorporates an updated digital user interface with an extended shade range from shade 8 to 13, covering all of the essential welding applications. The simple push button control panel makes it easy to select the exact shade, sensitivity and delay settings needed for the most challenging welding process. An external grind button locks the ADF to the passive shade 4 setting for quick grinding / finishing work without the need to remove the helmet. Pairing the helmet to ESAB's EPR-X1.1 PAPR system delivers TH3 level particulate protection, and the option to add A1B1E1 gas filtration with the available gas filter. The helmet's ventilation system drafts the air from the top of the headgear, providing a comfortable airflow during long welding hours.



### SPECIFICATIONS

Viewing Area 100 x 50 mm

Lens Shade 8 -13 Automatic

Power Supply Solar cell, Replaceable battery. (1\*CR2450 lithium). Alerts when low battery.

Sensors 4

Switch Time, from Dark to Light 0.1-0.9 s

Switch Time, at 23°C 0.07 ms

Classification 1/1/1/2

Standards CE EN379, EN175, EN12941, ANSI Z87.1 , CSA Z94.3, & AS/NZS 1338.1

Weight 700g

### ORDER INFORMATION

**SAVAGE A40 Air, Replaceable Battery, Black: Part No. 0700504102**

**EPR-X1.1 PAPR system with expandable hose: Part No. 0700500920**

